SpecToolV2 Connection Command HU7

V.1.001



- Coommand Outs



Command - DSUB 15PIN

HU7




Pinout HU7

Dsub15	Big plug	Small
1	-	
2	A = Bridge to 10Dsub	
3	8	
4	B = Bridge to 12Dsub	
5	21	
6	1	
7	1	
8	14	
9	20	
10	А	
11	7	
12	В	
13		
14		8
15		

LCD







Central Screen





GND	9
12V	10
Black	5
Black/White	1